instant connect

ICE Gateway Release Notes 3.4.0

Release notes for prerelease

Copyright © 2024, Instant Connect Software, LLC. All rights reserved. Document version 1841, produced on Friday, September 06, 2024.

main 90adc8bf40040649230176bbdd465f6261a2d8e0

ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. STA GROUP DISCLAIMS ALL WAR-RANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL INSTANT CONNECT LLC OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF STA GROUP OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Trademarks mentioned in this document are the properties of their respective owners.

Contents

1	New & Imp	roved	4
2	Fixes		4
3	Known Issues		5
	3.0.1	Telephony calls do not work after a fresh install. (ICE-21443)	5

1 New & Improved

These changes add new features or improve the functionality of existing ones:

- Use certstore instead of pem files. (ICE-16476)
- Update gateway to treat -1 as null for payload type translations. (ICE-20937)
- Update to engage version 1.238. (ICE-20867)

2 Fixes

These issues have been resolved in this version of the product:

- dfsig: launch dfsi during client chan0 tx causes restarts and one-way audio on chan1. Discovered in 3.4.0. (ICE-21114)
- issig: unexpected restart if quickly rename radio system AND gw. Discovered in 3.4.0. (ICE-21094)
- dfsig: change chan0 from taitfs to danielfs caused two diff ConnectReq msgs. Discovered in 3.4.0. (ICE-20953)
- issig: affiliation retries optimization for GROUP_NOT_FOUND. Discovered in 3.4.0. (ICE-21071)
- issig: core dump seen during launch. Discovered in 3.3.0. (ICE-18389)
- issig: sent GroupAffReq twice before receiving a GroupAffCnf response. Discovered in 3.4.0. (ICE-20920)
- Default log level is debug even after 5 hours of deployment. Discovered in 3.3.0. (ICE-20865)
- issig: 32ch inbound load test choppy audio and calls stopped streaming. Discovered in 3.3.0. (ICE-20029)
- dfsig: assign FS to different dfsig logic is broken. Discovered in 3.3.0. (ICE-20831)
- issig: one create key assoc to issi ch did not work. Discovered in 3.3.0. (ICE-20061)
- issig: one launch with 34 TG's resulted in one TG never affiliating. Discovered in 3.3.0. (ICE-18499)
- dfsig: secure comms completely broken. Discovered in 3.3.0. (ICE-20649)
- issig: create issi ch on diff radio system causes affiliation. Discovered in 3.3.0. (ICE-20646)
- dfsig: restarts during delete-recreate ch and remove-recreate FS assoc. Discovered in 3.3.0. (ICE-20576)
- dfsig: gw does not resume call when client dekeys during client ptt during radio ptt. Discovered in 3.2.0. (ICE-17582)
- issig: stop does not deregister and deaffiliates only some TGs. Discovered in 3.3.0. (ICE-20127)
- issig: tg failed affiliations reverted to 30min retries after 5min. Discovered in 3.3.0. (ICE-20013)

 issig: core dump when changing radiosys rfssid or systemid or wacnid. Discovered in 3.2.0. (ICE-17215)

3 Known Issues

These are issues known to exist in the product:

3.0.1 Telephony calls do not work after a fresh install. (ICE-21443)

3.0.1.1 Workaround Restart the telephony pod a second time after applying the license and configuring the DNS.

This document describes changes introduced between build 76038a1 to 674b78e.